Work Order ID 74950 Thursday, October 13, 2011 1:33:16 PM		Л		*74950*				Page 1			
Item ID: Revision ID: Item Name:	D3272-1 Step		A	Accept	*N900	040	100)* Se	etup Star Stop	1 31	S1* S2*
Start Date: Required Date: Reference:	_	y: 10.00 ety: 10.00	*10* *10*		Cust Item II Customer:	D:				, ,	
Approvals:	Process Plan:		Date:	Tooling: SPC (Y/N):		te:		R	un Star Stop	" [V]	R1* R2*
Sequence ID/ Work Center ID	Operatio Descripti			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr			***			,				
D3272	Rev B										
*1 \\ \tage \text{Fab} Large Fab	Large Fab		ONE END BEFORE CUT		H11.	10.9	2/	10	\$		
ý.		table setup D			ing cutting						

110

QC6- Inspect dimensions to drawing

0.00

110 _{QC}

Memo

Quality Control

0.00

D	art	Δe	ros	pa	ce	Ltd
_	411	\neg		\sim		

Dart Ae	rospace	Lta			-				•
W/O:			WO	RK ORDER CHANGE	S				-
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
!									
Part No		PAR #:							
	Re	esolution:						Date: _	
NCR:		V	VORK ORDE	R NON-CONFORMAN	NCE (NCI	?) 			
DATE	STEP	Description of NC Section A	Corrective Action S Initial Action Description Chief Eng Chief Eng		Sign Date	& Sec			Approval QC Inspector
,,,,,									

W	ork	Orde	r ID	74950
---	-----	------	------	-------

Quality Control

74950

Page 2 Thursday, October 13, 2011 1:33:16 PM D3272-1 Item ID: Accept *N900040100* Setup Start **Revision ID:** Item Name: Step *10* 10/13/2011 **Start Qty: 10.00 Start Date: Cust Item ID:** Reg'd Oty: 10.00 **Required Date:** 10/19/2011 *10* **Customer:** Reference: Run Start Approvals: Process Plan: Date: Tooling: Date: Stop SPC (Y/N): Date: Date: Sequence ID/ **Operation** Set Up/ Tool ID Tool # Plan Reject Reject Insp. Accept Work Center ID **Description** Code Qty Number Stamp Qty **Run Hours** Identify as per dwg & Stock Location: LA 120 0.00 M11.10.21 *120* 0.00 Packaging Memo Packaging 130 QC21- Final Inspection - Work Order Release 0.00 *130* OC 0.00 Memo

M 10 24 Sp. 10)

Dart Ae	rospace	Ltd								*
W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No):	PAR #:	Fault Cate	gory:	NCF	R: Yes I	No DQ	A:	Date: _	
		Disposition:		QA:	QA: N/C Closed:			Date:		
NCR:			WORK ORD	ER NON-CONFORM	IANCE	(NCR)			
		Description of NC		Corrective Action Sec	ction B Verification			cation	Approval	Approval
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	I	tion C	Chief Eng	QC Inspector

Thursday, October 13, 2011 1:33:21 PM

Work Order ID: 74950

74950

Primary

Item Location

Last

Location

Parent Item:

D3272-1

D3272-1

Parent Item Name:

Component Item ID/

Step

Start Date: 10/13/2011

Required Date: 10/19/2011

Start Qty: 10.00

Required Oty: 10.00

Comments:

IPP Rev:A

Item ID

New Issue 07-06-09

Purch

Manufactured

Replacement Mfg/

JLM

Bin

No

Route Seq ID

Unit of Measure Hand

Qty on

Qty per Kit Total

Qty

Date Issued

Status

Page 1

D2622-120C

Item Name

D2622-120C

Step Extrusion

100 Each 120.2000

**

Qty

Issued

<u>Location</u>	Loc Qty	Loc Code	
HALL	110.5		
64409	6		
68293	0.5		
72131	104		10
WA	9.7		
46910	2		
66970	7.7		

1

	HANGES				
PROCEDURE CHANGE	Ву	Date	Qty	Qty Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-		
					<u> </u>
_	PAR #: Fault Category:			PAR #- Fault Category: NCR: Yes No DQA:	Prod Mgr

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)									
	T			Corrective Action Section B	,	Verification	Approval Chief Eng	Approval QC Inspector				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C						
			:									
· · · · · · ·												
			-									

Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____



DESIG	P	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAD	
CHEC	SED _	APPROVED	DRAWING NO.	REV. B
(E	t	D3272	SHEET 1 OF 3
DATE			TITLE	SCALE
07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	

07 06 04

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
			` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE

2) WELD PER DART QSI 004

3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4

- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

SUBJECT TO AMENDMENT ENGINEERING RETURN TO

Dart Aerospace Ltd WORK ORDER CHANGES W/O: Approval Chief Eng / **Approval** Date Qty PROCEDURE CHANGE By DATE **STEP** QC Inspector Prod Mar Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B Verification **Approval Approval Description of NC** Sign & DATE **STEP Action Description** Chief Eng QC inspector Initial Section C Section A Date Chief Eng Chief Eng

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE


Dart	Aero	space	Ltd
------	------	-------	-----


W/O:			WORK ORDER	CHANGES				
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								,
						<u>. l</u>		
Part No	o:	PAR #:	Fault Category:	NCR: Ye	s No DG	A:	Date: _	
				QA: N/C	Closed:		Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
			Corrective Action Section B			Verification	Approval	Approval	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector	
							·		



	1		
DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
CHECKED	APPROVED /	DRAWING NO.	REV. B
LE		D3272	SHEET 3 OF 3
DATE		TITLE	SCALE
07.05.18		STEP ASSEMBLY, HI LONG	1:20





Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart Aerospace Ltd W/O:		WORK ORDER CHANGES		Date	Qty	Approval Chief Eng /	Approval QC Inspector
DATE	STEP	PROCEDURE CHANGE	Ву			Prod Mgr	

		NCR: Yes No	DQA:	Date:
Part No: PAR #:	_ Fault Category:	QA: N/C Closed		Date:
Resolution:	Disposition:	NCE (NCR)		_

NCR:			WORK ORDER NON-CONFORMANCE (NCR) Corrective Action Section B			Verification	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Ciller Ling	
			Olinoi aa					
*								
					7			
• 1 4 .								
·							·	
								<i>y</i> –
٠								,
<u> </u>	+						, ,	\wedge
							/	Q3ldO